



**Hubshell**  
148

**A** NDS Flange  $\varnothing$   
58mm

**B** NDS Center to Flange  
37mm

**C** DS Center to Flange  
23mm

**D** DS Flange  $\varnothing$   
60mm

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*