



Hubshell
110

A NDS Flange \varnothing
47mm

B NDS Center to Flange
29mm

C DS Center to Flange
42mm

D DS Flange \varnothing
42mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing